

PROJECT SHEET

X-Press It metal leaf candle



STEP BY STEP

WHAT YOU'LL NEED

- X-Press It Gold Size
- X-Press It Metal Leaf
- Candle
- Paint Brushes



INSTRUCTIONS



Step 1: Using a clean paint brush, apply a thin layer of X-Press It Gold Size on the areas you want to cover with the Metal Leaf. Allow the Gold Size to dry for 15 minutes or until it becomes tacky.



Step 3: Once fully covered with Metal Leaf, use a clean, soft brush to dust off the excess leaf very delicately.



Step 2: Delicately place X-Press It Metal Leaf Flakes onto the area where you have applied the Gold Size. (You can use tweezers or your fingers to do this).



Step 4: Fill in any gaps you may have missed using the first three steps. Your project is completed and ready!

**For decorative purposes only. Do not use light and use candle once decorated.*